

CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

2. Scientific-Methodical Classification of Methods for Investigating Chemical Composition of Materials	15
Chemical Methods for Analysis	15
Physicochemical Methods	17
Physical Methods	18
3. Industrial (Plant) Classification of Methods for Chemical Analysis	20
Ultimate Methods	20
Rapid (Proximate) Methods	21
Control Methods	22
Arbitration Methods	22
4. Unification of Technical Methods for Chemical Analysis	24
5. Accuracy and Reproducibility of Analytical Methods for Production Control	26
6. Charts of Allowable Deviations in Determination of Some Elements in Cast Irons and Steel	30
7. Standard Samples of Ores, Slags, Cast Irons, Steels, Ferroalloys, and Nonferrous Metals for Chemical and Spectrum Analysis	34
8. Chemical Composition of Some Standards	38
B. Physicochemical Methods of Analysis	
1. Brief Information on Potentiometric Method	42
2. Brief Information on Colorimetric Method of Chemical Analysis and Instructions for Using Photoelectric Colorimeter	50
3. Brief Information on Internal Electrolysis	66
4. Brief Information on Polarographic Method	69
C. Preparation of Representative Sample of Materials for Chemical Analysis	
1. Selection of Initial Representative Sample	75
2. Selection of Final Laboratory Sample	87
3. Rules for Selecting Laboratory Samples of Metal for Chemical Analysis with Aid of Drilling, Milling, and Crushing in a Mortar	88
4. Rules for Sending Samples to Analytical Laboratory	90
D. Preparation of Small Parcels of Material for Chemical Analysis	
1. Removal of Organic Admixtures; Obtaining an Air-Dry Sample	91
2. Methods of Decomposing Materials for Analysis	92
3. Volatility of Salts of Certain Metals	97
4. Table of Most Used Fluxes	99
5. Methods for Chemical Separation of Elements	102

FERROUS METALLURGY SECTION**Analysis of Metallurgical Raw Material and Slags****A. Analysis of Iron and Other Ores**

1. Determination of Iron by Titration with Potassium Permanganate	104
2. Determination of Iron by Bichromate Method	109
3. Determination of Silicon Dioxide in Iron and Manganese	112
4. Determination of Aluminum Oxide	114
5. Determination of Manganese by Oxidation With Potassium Permanganate	116

- 2 -

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

6. Determination of Phosphorus in Iron and Manganese Ores	120
Gravimetric Method	122
Volumetric (Alkaline) Method	123
7. Determination of Sulfur	124
8. Determination of Zinc in Iron Ore	126
a. Determination of Zinc With Preliminary Separation of Iron	126
b. Determination (Precipitation) of Zinc in Presence of Iron	129
9. Determination of Chromium (in Chromium Ore)	130
10. Determination of Arsenic	131
 B. Analysis of Titanomagnetite Ore	
1. Determination of Titanium: Colorimetric Method	132
Volumetric Method	135
2. Determination of Vanadium: Volumetric Method	139
 C. Analysis of Wolfram Ore (Sheelite)	
Determination of Wolframic Acid	141
 D. Analysis of Fluorspar	
1. Determination of Calcium Fluoride for Especially Precise Analysis	142
Determination of Calcium Fluoride for Ultimate and Rapid Analysis	144
2. Determination of Silica	145
3. Determination of Silica and Fluorine in Simultaneous Occurrence	146
 E. Analysis of Limestone (Dolomite, Magnesite)	
1. Determination of Loss on Heating	149
2. Determination of Silica	149
3. Determination of Total Sesquioxides ($\text{Fe}_2\text{O}_3 + \text{Al}_2\text{O}_3$)	150
4. Determination of Calcium Oxide	150
5. Determination of Magnesium Oxide	151
6. Determination of Carbon Dioxide	151
 F. Analysis of Slag	
1. Determination of Silica	153
2. Determination of Aluminum Oxide: Phosphate Method	154
3. Determination of Calcium Oxide: Volumetric Method	155
4. Determination of Magnesium Oxide	158
In Form of Pyrophosphate.	158
With Hydroxyquinoline	159
5. Determination of Calcium Oxide by Volumetric Semi-micromethod (Accelerated Method)	161
6. Determination of Free Calcium Oxide: Glycerin Method	163
Glycol Method	165
7. Determination of Calcium Carbide	166
8. Determination of Calcium Fluoride	167
9. Determination of Calcium Sulfide (Sulfide Sulfur)	169
10. Determination of Ferrous Oxide	170
11. Determination of Metallic Iron	172
12. Determination of Ferric Oxide	175
13. Determination of Manganous Oxide: Persulfate-Silver (Arsenite-Nitrite or Arsenite) Method	176

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL
CONFIDENTIAL

50X1-HUM

- | | |
|-------------------------------------|-----|
| 14. Determination of Chromium Oxide | 177 |
| 15. Phase Analysis | 177 |

Analysis of Ferroalloys

- | | |
|--|-----|
| A. Analysis of Ferrosilicon (With Silicon Content of 30-90%) | |
| 1. Determination of Silicon | 178 |
| Method of Fusing | 178 |
| Method of Decomposing a Sample With Mixture of Hydrofluoric and Nitric Acids | 181 |
| By Specific Weight | 181 |
| 2. Determination of Aluminum (Titanium and Zirconium) | 183 |
| 3. Determination of Carbon | 189 |
| 4. Determination of Sulfur | 189 |
| B. Analysis of Ferromanganese | |
| 1. Determination of Manganese | 189 |
| Persulfate-Silver Method | 189 |
| Chlorate Method | 190 |
| 2. Determination of Phosphorus | 191 |
| 3. Determination of Carbon | 192 |
| 4. Determination of Sulfur | 192 |
| C. Analysis of Ferrochromium | |
| 1. Determination of Chromium | 192 |
| Iodometric Method | 192 |
| Persulfate-Silver Method | 194 |
| 2. Determination of Chromium and Iron: Potentiometric | 196 |
| Noncompensating Method | 196 |
| Determination of Chromium | 197 |
| Determination of Iron | 198 |
| 3. Determination of Silicon: Hydrochloric Acid Method | 199 |
| 4. Determination of Silicon and Chromium from Single Sample | 199 |
| 5. Determination of Carbon | 199 |
| 6. Determination of Sulfur | 199 |
| D. Determination of Ferrowolfram | |
| 1. Determination of Wolfram | 199 |
| 2. Simultaneous Determination of Wolfram and Silicon | 201 |
| 3. Determination of Phosphorus | 202 |
| Method of Fusing | 202 |
| Method of Dissolving | 203 |
| 4. Determination of Aluminum | 204 |
| 5. Determination of Copper | 205 |
| 6. Determination of Carbon | 206 |
| 7. Determination of Sulfur | 206 |
| E. Analysis of Ferromolybdenum | |
| 1. Determination of Molybdenum | 206 |
| In Form of Lead Molybdate | 206 |
| Volumetric Permanganate Method (Reduction of Molybdenum with Lead) | 208 |
| 2. Determination of Phosphorus | 209 |
| 3. Determination of Copper | 210 |
| 4. Determination of Carbon | 212 |
| 5. Determination of Sulfur | 212 |

- 4 -

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

F. Analysis of Ferrovandium

- | | |
|---|-----|
| 1. Determination of Vanadium | 212 |
| Method of Direct Titration With Ferrous Sulfate Using | |
| Oxidation-Reduction Indicator | 212 |
| Method of Potentiometric Titration | 213 |
| Persulfate Method | 214 |
| 2. Determination of Phosphorus | 215 |
| 3. Determination of Aluminum (Total) | 217 |
| 4. Determination of Carbon | 218 |
| 5. Determination of Sulfur | 218 |

G. Analysis of Ferrotitanium

- | | |
|--------------------------------|-----|
| 1. Determination of Titanium | 219 |
| 2. Determination of Phosphorus | 220 |
| 3. Determination of Carbon | 221 |
| 4. Determination of Sulfur | 221 |

H. Analysis of Ferrozirconium (Ferrosilicozirconium, Silicozirconium)

- | | |
|--|-----|
| 1. Determination of Zirconium by Phenylarsonic Acid Method | 221 |
| 2. Determination of Zirconium and Titanium | 223 |
| 3. Determination of Aluminum | 225 |
| 4. Determination of Iron | 225 |
| 5. Determination of Zirconium and Aluminum by Phosphate Method | 226 |
| 6. Determination of Silicon | 226 |
| 7. Determination of Carbon | 227 |
| 8. Determination of Sulfur | 227 |

I. Analysis of Ferrocolumbium

- | | |
|---|-----|
| 1. Accelerated Analysis of Ferrocolumbium (in Absence of Noticeable Quantities of Tantalum): Determination of Columbium, Titanium, Aluminum, Iron | 228 |
| 2. Determination of Carbon | 230 |
| 3. Determination of Sulfur | 230 |

J. Analysis of Ferroboron

- | | |
|--|-----|
| 1. Determination of Boron: Volumetric Method | 230 |
| 2. Determination of Carbon | 233 |
| 3. Determination of Sulfur | 233 |

Analysis of Cast Irons and Steels

- | | |
|--|-----|
| 1. Determination of Carbon (Total) | 234 |
| Casometric (Absorption-Volumetric) Method | 234 |
| Barium Oxide Volumetric Method | 243 |
| Absorption-Gravimetric Method | 246 |
| 2. Determination of Graphite and Temper Carbon | 251 |
| 3. Determination of Sulfur | 253 |
| Iodometric Method (by Combustion in Oxygen Flow) | 253 |
| Method of Distilling off in the Form of Hydrogen Sulfide | 259 |
| 4. Determination of Phosphorus | 266 |
| Volumetric (Alkaline) Method | 272 |
| Gravimetric Molybdate Method | 273 |
| Gravimetric Molybdate-Lead Method | 273 |
| In Presence of Wolfram and Silicon | 274 |
| In Presence of Vanadium | 275 |

- 5 -

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL
CONFIDENTIAL

50X1-HUM

In Presence of Arsenic	275
Photocolorimetric Method	276
5. Determination of Manganese	279
Persulfate-Silver Method	280
Persulfate-Silver (Arsenite-Nitrite and Arsenite) Method	
in Presence of Chromium	283
a. Separation of Chromium With Zinc Oxide	283
b. Separation of Chromium With Perchloric Acid	284
Persulfate-Silver Method in Presence of Cobalt	285
Bismuthate-Arsenite Method	286
Bismuthate-Permanganate Method	287
Chlorate Method	289
6. Determination of Silicon	291
Perchloric Acid Method	292
Sulfuric-Nitric Acid Method	295
Photocolorimetric Method	297
7. Determination of Wolfram	300
Gravimetric Determination for Accelerated Analysis	301
Gravimetric Cinchonine Method	302
Volumetric (Alkaline) Method	303
Photocolorimetric Method	305
a. Method I - Reduction with Stannous Chloride (or Titanium Trichloride) in Presence of Potassium Thiocyanate	306
b. Method II - Same (Accelerated)	307
c. Method III - With Hydroquinone (Macro- and Micro-determination)	307
8. Determination of Chromium	308
Persulfate-Silver Method	308
Iodometric Method (in Absence of Vanadium))	311
9. Determination of Chromium and Vanadium by Potentiometric Noncompensating Method	314
10. Determination of Chromium or Chromium and Vanadium: Volumetric Semimicromethod Using Phenyl Anthranilic Acid as Oxidation-Reduction Indicator	317
Colorimetric Method (at Contents to 0.15%)	319
11. Determination of Vanadium Using Phenyl Anthranilic Acid as Oxidation-Reduction Indicator	321
12. Determination of Nickel	323
Gravimetrically According to Chugayev (in Absence of Cobalt)	326
With Dimethylglyoxime-Volumetrically	329
Gravimetric Determination in Presence of Cobalt	329
Volumetric (Cyanometric) Method in Steels Containing No Copper (Over 0.05%) or Cobalt	330
Cyanometric Method in Presence of Copper and Cobalt	331
Photocolorimetric Method (With Dimethylglyoxime)	331
Determination of Nickel and Copper by Polarographic Method	334
13. Determination of Cobalt	336
Il'inskiy Method	336
Potentiometric (Noncompensating) Method	338
Photocolorimetric Method	342
14. Determination of Molybdenum	344
With Alphaazobenzoinoxime (Cupron)	344
Colorimetric Method With Extraction With Ether	346
Colorimetric Method Without Extraction With Ether	349
15. Determination of Copper	351
By Precipitation With Sodium Thiosulfate With Subsequent Iodometric or Electrolytic Completion of Analysis	351

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

Electrolytic Method, Including Internal Electrolysis	353
Iodometric Method	355
Electrolytic Method Without Preliminary Separation of Iron and Other Elements (for Accelerated Analysis)	355
16. Determination of Titanium and Aluminum	356
Determination of Titanium and Aluminum by Cupferron Method Using Mercury Cathode	356
Determination of Titanium in Presence of Vanadium	360
Determination of Titanium and Aluminum by Hydrogen Sulfide-Cupferron Method	360
Determination of Titanium by Cupferron-Colorimetric Method	363
Determination of Titanium in Titanium Steels (such as Stainless Steels)	364
Determination of Titanium in Cast Irons	365
Determination of Aluminum by Phosphate Method	366
17. Determination of Zirconium	369
Phenylarsonic Method	369
Phosphate Method	370
Cupferron-Phosphate Method	372
18. Determination of Columbium and Tantalum	373
Gravimetric Method for Precise Analysis	373
Gravimetric Method for Accelerated Analysis	377
Determination of Columbium in High-Chromium (Stainless and Heat-Resistant) Steels	379
19. Determination of Beryllium by the Oxyquinoline Method	379
20. Determination of Lead	383
Chart: Conditions for Precipitation of Separate Metals with Oxyquinoline	384
a. Gravimetric Method:	
In Form of Lead Sulfate	386
In Form of Lead Chromate	387
In Form of Lead Molybdate	388
b. Indirect Colorimetric Method	388
21. Determination of Arsenic: Method of Reduction With Calcium Hypophosphate	389
22. Determination of Combined Nitrogen by Distilling Off in Form of Ammonia	392
23. Determination of Oxygen (Ferrous Iron) in Liquid Steel by Aluminum (Acid) Method; Simultaneous Determination of Aluminum Oxide and Metallic Aluminum	402
24. Qualitative Detection of Alloying Elements: Detection of	
Chromium	407
Wolfram	407
Vanadium	407
Nickel	408
Cobalt	408
Molybdenum	409
Titanium	409
Beryllium	410
Lead	410
Selenium	411

NONFERROUS METALLURGY SECTIONAnalysis of Nonferrous Metals and Alloys**A. Analysis of Metallic Nickel****1. Determination of Nickel**

412

- 7 -

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

a. Electrolytic Method	412
b. Gravimetric Method (With Dimethylglyoxime)	414
2. Determination of Cobalt	416
3. Determination of Copper and Silicon	417
4. Determination of Zinc	418
5. Determination of Manganese	419
6. Determination of Iron	420
7. Determination of Aluminum	421
8. Determination of Calcium and Magnesium	422
9. Determination of Carbon	423
10. Determination of Sulfur	423
 B. Analysis of Copper Alloys (Bronze, Brass, and Others)	
1. Determination of Copper	423
2. Determination of Aluminum (Iron)	426
Oxyquinoline Method	427
Phosphate Method	428
3. Determination of Iron	428
Gravimetric Cupferron Method	429
Volumetric Method	430
4. Determination of Manganese	430
Bismuthate Method	430
Persulfate-Silver (Arsenite) Method	431
5. Determination of Tin	431
Iodometric Method	432
Gravimetric Method	433
6. Determination of Lead	433
Electrolytic Method	434
In Form of Lead Sulfate	434
7. Determination of Zinc	435
8. Determination of Phosphorus	437
Gravimetric Method for Precise Analysis	437
Volumetric Method for Accelerated Analysis	438
 C. Analysis of Aluminum Alloys	
1. Determination of Silicon: Acid Method	438
2. Determination of Silicon in Silumin	440
3. Determination of Iron	441
4. Determination of Calcium and Magnesium	442
5. Determination of Copper	443
Iodometric Method	444
Electrolytic Method	444
Internal Electrolysis	445
6. Determination of Zinc	445
Content less than 1%	445
Content more than 1%	447
Polarographic Method (Content from 0.03 - 10%)	447
7. Determination of Tin	449
8. Determination of Manganese	450
9. Determination of Titanium	451
10. Determination of Nitrogen	452
11. Determination of Sulfur	452
 D. Analysis of Babbitt	
1. Determination of Antimony	452
2. Determination of Tin	453
3. Determination of Tin in Presence of Copper (1 - 10%)	455
4. Determination of Calcium and Sodium	456

- 8 -

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

Appendix

1. Weighing on an Analytical Balance	458
2. Rules for Handling Laboratory Platinum Equipment	461
3. Regulations for Using Perchloric Acid	462
4. Certain Regulations for Preventing Accidents in Analytical Laboratories	463
5. Recovery of Some Expensive Reagents	467
6. Useful Compounds	468
7. Concentrations and Densities (Specific Weights) of Chief Acids at 20°C	470
8. Concentrations and Densities of Alkali Hydroxide and Ammonia Solutions at 20°C	472
9. Table of Conversion Factors for Gravimetric Analysis	473
10. Table of Conversion Factors for Volumetric Analysis	477
11. Atomic Weights of Elements for 1947	478
12. Correction Factors for Atmospheric Pressure and Temperature in Gasometric Method for Determination of Carbon	480

Bibliography [73 titles]

481

- E N D -

- 9 -

CONFIDENTIAL

CONFIDENTIAL